


# CORNER RECORD

BK

59

PG

86

APN No. 99B-7985-1-6 (Optional)Document Number CR 6099Unincorporated Murray TownshipCounty of Alameda, CaliforniaBrief Legal Description In Patterson Pass Rd., MP 6.4

## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☐  
Rancho ☐ Other ☐  
Date of Survey 03/27/2014

## COORDINATES (Optional)

N. 2,076,035.1  
E. 6,245,654.1  
Zone 3 NAD27 ☐ NAD83 ☒  
NAD 83 Epoch 2011.00  
Elev. \_\_\_\_\_

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Not Found ☐

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to ESTABLISH \_\_\_\_\_ / REESTABLISH \_\_\_\_\_ the position of an existing monument PRIOR ☒ / SUBSEQUENT \_\_\_\_\_ to street or highway reconstruction. (Use this portion only when applicable.)

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Using record locations from nearby CSRC Published monuments P228, P230, P255 and P257, a field survey with STATIC-GPS methods was conducted establishing locations for the found 1" Rebar monuments.

A description of the physical condition of the monument as found and as set or reset:

See sketch on Page 2.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 7/23 20 14.

Signed Robert A. Machado L.S. or R.C.E. Number 7380



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-23 20 14 and examined and filed 7-27-2014.

Signed [Signature] Title County Surveyor



County Surveyor's Comment \_\_\_\_\_

Job Number: R26213

Spec No: \_\_\_\_\_

