


**CORNER RECORD**Document Number **CR 9314**City of Oakland (APN 40A-3441-18-2)County of Alameda, CaliforniaBrief Legal Description Monument in Greenly Drive +/- 80 feet northwesterly of Circle Hill Drive, near 7200 Greenly Drive**CORNER TYPE**

Government Corner ☐ Control ☒  
 Meander ☐ Property ☐  
 Rancho ☐ Other ☐

Date of Survey October 13, 2016**COORDINATES (Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29 ☐ NAVD88 ☐  
 Meas. Units: Metric ☐ Imperial ☐

**Pre-Construction (water line) Corner Record**

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
 Found monument on Greenly Drive endangered by planned waterline construction referenced prior to  
 construction of new waterline (see page 2). The purpose of this corner record is to preserve possible evidence  
 only, no attempt was made to determine the relationship to property, centerline or right of way lines

A description of the physical condition of the monument as found and as set or reset:

Monument was found in good condition and referenced with set RP's representing intersecting lines (see page 2)


Reference EBMUD Field Book 4593, Page 67 (Burke/Zavala)

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with  
 the Professional Land Surveyor's Act on NOVEMBER 30, 2016

Signed

P.L.S. or R.C.E. No.

7263**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 30 NOVEMBER, 2016  
 and examined and filed 17 JANUARY, 2017

Signed

P.L.S. or R.C.E. No.

6843

Title

COUNTY SURVEYOR

County Surveyor's Comment:

